FREEDOMTUFF™ FT-9115



PRODUCT DESCRIPTION

FT-9115 is a fast-setting, two-component modified urethane concrete repair material. Its thixotropic consistency allows for vertical repairs without sagging.

USES

- Rapid setting concrete primer
- Rapid setting, high strength concrete patching and repair material
- Vertical bug hole filler

ADVANTAGES

- Excellent abrasion resistance
- · High impact resistance
- Low odor
- Meets SCAQMD requirements
- Minimal prep/down time
- Quick set time
- Non sag
- USGBC LEED, EQ Credit 4.3: Low-emitting VOC Compliant Materials

COLOR

WHITE

Note: Due to its chemical composition, FT-9115 will discolor when exposed to UV radiation.

TYPICAL PHYSICAL PROPERTIES

| Property | Test Method | Value |
|------------------------|----------------|--------------------|
| Mix Ratio by Volume | NA | 1:3 |
| Pot Life @ 68°F | ISO 9514 | 15 minutes ± 3 |
| Tack Free Time @ 68°F | ASTM D1640 | 1-2 hours |
| Recoat Window | Internal | 6 hours |
| Pedestrian Traffic | Internal | 4 hours |
| Vehicular Traffic | Internal | 12 hours |
| Solids Content | ASTM D6511 | 100% |
| VOC | ASTM D6511 | 0 g/L |
| Shore Hardness | ASTM D2240 | 75D ± 3 |
| Tensile Strength | ASTM D412 | 2,000 psi ± 200 |
| Elongation | ASTM D412 | 80% ± 20 |
| Tear Strength, Die C | ASTM D624 | 150 pli ± 30 |

The values stated in this Product Data Sheet are based on system processing under controlled laboratory conditions. Equipment configuration and/or field application conditions may produce variances in the installed product values

Page 1 of 2

FREEDOMTUFF™ FT-9115



SURFACE PREPARATION

Provide clean, dry, and sound concrete substrate. Concrete shall be allowed to cure for a minimum of 28 days.

Prepare concrete surfaces in accordance with SSPC-SP13/NACE No. 6 and achieve a Concrete Surface Profile of at least 3, measured using ICRI CSP Chips.

After surface preparation and prior to the application of Freedom Chemical Corporation products, test surface tensile strength of prepared concrete surfaces in accordance with ASTM D7234 and/or ASTM C1583. Minimum surface tensile strength shall be 300 psi. Refer to SSPC-SP13/NACE No. 6, Section 6, Table 2 for additional information.

Grinding is only permitted in areas that are inaccessible to standard abrasive blast equipment.

COVERAGE RATES

Material coverage rates shall be in accordance with project specification requirements or Freedom Chemical Corporation's Installation Procedure document(s), whichever is more stringent.

PACKAGING

1-gallon kit:

Part A: 0.25 gallons liquid

• Part B: 0.75 gallons liquid

MIXING & APPLICATION

Premix part B for 2 min. Add part A and mix for several minutes. Product will increase in viscosity quickly. Continue mixing without entraining air until it becomes consistent in color and texture. The product will become paste consistency.

CLEAN UP

User is responsible for reading, understanding, and following all recommendations on SDS. Dispose of all packaging and containers in accordance with local, state, and federal laws and regulations. Excess liquid materials should be mixed and allowed to cure. Once cured, dispose of cured material in accordance with local, state, and federal laws and regulations.

LIMITATIONS

Care shall be taken when applying Freedom Chemical Corporation products over substrates containing trapped moisture and/or where moisture vapor drive is present (i.e., metal pan decks, split slab membranes, etc.). Refer to Installation Procedure document(s) for substrate treatment prior to placement of any coatings.

Excess moisture vapor in concrete slabs may cause polyurea coating to delaminate, discolor, and/or cure improperly.

SHELF LIFE & STORAGE

Shelf life is one (1) year from the date of manufacture in original, unopened, factory-sealed containers under specified storage conditions.

Shipping and storage temperatures is 65°F to 90°F at (or below) 50% Relative Humidity. Avoid freezing temperatures. Do not store containers directly on ground. Always store on pallets or otherwise elevated.

Do not open containers until ready to use. Partially filled containers should be purged of air using nitrogen blanketing and sealed tightly when not in use.

Revision 0925-C